Tuesday, 03/06/2008 1:03:23 PM

Julie Lecocq

### **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Job Number

**Estimate Number** 

: 39667A : 12480

P.O. Number

This Issue Prsht Rev. : 03/06/2008

: NC

First Issue

: //

: MACHINED PARTS Type

: 38021A **Previous Run** 

Written By

Comment

Checked & Approved By

6.03 : Est Rev:A New Issue 06-06-28 JLM

**Drawing Name** 

**Part Number** 

**Drawing Number** 

: D3529 REV A : N/A

: D35291

**Project Number Drawing Revision** 

Material **Due Date** 

: 20/06/2008

: R44 BEARPAW

Qty:

**Additional Product** 

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

MUHMWB10

UHMW 1" Black

Comment: Qty.:

1.3283 sf(s)/Unit Total: 10.6260 sf(s)

blank: 13.5" x 13.000" x 1.00" thick (+0.030/-0.000)

Material: Black UHMW 1"(MUHMWB10)

Batch: M / 080/3

2.0

MFG ENGINEERING

MFG ENGINEERING



Program Batch Number

3.0

HAAS1

HAAS CNC VERTICAL MACHINING #1



**Comment: MFG ENGINEERING** 

Comment: HAAS CNC VERTICAL MACHINING #1

1-Inspect material for defects or damage prior to machining

2-Machine as per Folio FA645 and Dwg D3529

3-Deburr

4.0

1

QC2

INSPECT PARTS AS THEY COME OFF MACHI



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

# **Dart Aerospace Ltd**

W/O: WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
					<u> </u>						

Part No:	PAR #:	Fault Category:	NCR: Yes	No	DQA:	Date:
			QA: N	1/C C	losed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B	3	Verification				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
							-			
						_	1			
						,				
							٠			
							·			

NOTE: Date & initial all entries

Tuesday, 03/06/2008 1:03:23 PM Date: User: 3 Julie Lecocq **Process Sheet** Drawing Name: R44 BEARPAW Customer: CU-DAR001 Dart Helicopters Services Job Number: 39667A Part Number: D35291 Job Number: Seq. #: **Machine Or Operation:** Description: SECOND CHECK 5.0 QC8 Comment: SECOND CHECK 6.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock 35667 Location: FINAL INSPECTION/W/O RELEASE 7.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Ae	rospace	e Lta							
W/O:			V	VORK ORDER CHANGE	S		,		
DATE	STEP	PRO					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			ś						
Part No	·	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQA:		_ Date: _	
					QA: N/	C Closed:		_ Date:	
NCR:		,	WORK OR	DER NON-CONFORMAN	NCE (NCR)	رد		:	
	0750	Description of NC	Corrective Action Section			ion	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
								•	
.,,									
									-

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	3916671
Description: Bearpaw	Part Number:	D3529-1
Inspection Dwg: D3529 Rev: A		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

	spection Sheet wing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Α	5.50	+/-0.030	5.50	V			
В	0.07 x 45°	+/-0.030 x 0.5°	0.040				
С	R0.25	+/-0.030	R 0,25	/			
D	0.250	+/-0.010	0.240	<b>V</b>			
E	0.625	+/-0.010	0.622	<b>V</b>			
F	0.950	+/-0.010	0.949	·/			
G	1.63	+/-0.030	1.620	1			
Н	12.14	+/-0.030	12.140	V		tape	
J	5.70	+/-0.030	5.710	٧			
K	0.375	+/-0.010	0.369				·
L	0.525	+/-0.010	0.519	<b>/</b>			
М	0.13 x 45°	+/-0.030 x 0.5°	0. 130 × 45				
N	R0.50	+/-0.030	R 0.50	>	,		
0	12.76	+/-0.030	12.76			tape	
Р	3.38	+/-0.030	3,373	\			
Q	3.75	+/-0.030	3.375	~			
R	5.187	+/-0.010	5.190				
S	5.25	+/-0.030	5,252	<b>\</b>			
Т	7.13	+/-0.030	7.128	>			
U	Ø0.260	+0.006/-0.001	\$0.260	1			
V	0.30	+/-0.030	0,300	/			
W	0.93	+/-0.030	0.928	/			
Х	1.30	+/-0.030	1.271	V			

Measured by:	M.A	Audited by:	Prototype Approval:	N/A
Date:	08/06/09	Date: 08/06//0	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.05.01	New Issue	KJ/JLM LA	
В	08.05.06	Dimension I removed	KJ/DD 🛠	


## **Dart Aerospace Ltd**

	· oopao.	, <del>-</del> 10								
W/O:		· · · · · · · · · · · · · · · · · · ·	.v. WC	ORK ORDER CHANG	SES					
DATE STEP		PROCEDURE CHANGE			В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	,			·						
Part No	•	PAR #:	Fault Cate	gory:					Date:	
<del></del>		V	NOBK OBDI	ER NON-CONFORM				u	_ Date	
NCR:	1		·							
DATE	STEP	<b>Description of NC</b> Section A	Initial Action Description Chief Eng Chief Eng		ion Sign & Date		Verification Section C		Approval Chief Eng	Approval QC Inspector
							·			
						<del></del>				

NOTE: Date & initial all entries







#### **D3529-1 R44 BEARPAW**

SHOP COPY

#### NOTES:

RETURN TO

1) MATERIAL: UHMW BLACK PER SPEC CONTROL DRAWING D2689, 1.00 THICK (MACHINE TO 0.950) FINGINEERING 2) FINISH: NONE UNCONTROLLED C UNCONTROLLED COPY

3) PART IS SYMMETRIC ABOUT € 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

ALL DIMENSIONS ARE IN INCHES
BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX
ENGRAVE LOGO TO MAX DEPTH OF 0.012 AT LOCATION SHOWN

8) ENGRAVE PART AND BATCH NUMBERS TO MAX DEPTH OF 0.010 AT LOCATION SHOWN


SUBJECT TO AMENDMENT

WITHOUT NOTICE

#### **COPYRIGHT © 2007 BY DART AEROSPACE LTD**




DESIGN	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA			
CHECKED	APPROVED	D3529	REV. A SHEET 2 OF 2		
DATE 07.	01.04	R44 BEARPAW	SCALE 1:4		



**SECTION A-A** 

**SECTION B-B** 

SECTION C-C



THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.